

## REHABILITATION OF THE ALUTO PILOT GEOTHERMAL POWER PLANT

**Markos Melaku and Bob Thomasson**

*Geothermal Development Associates*

*mmelaku@gdareno.com, bthomasson@gdareno.com*

### SUMMARY

The Aluto Pilot Geothermal Power Plant was built and commissioned in late 1998 but stopped operation after a very short period due to various technical problems. Failure of the heat exchanger tubes caused the premature shutdown of the OEC unit after about a year of operation. A number of resource related problems also caused reduction in the power output of the GCCU which was eventually shut down in 2002.

The rehabilitation of the plant began in early 2006 which included overhaul of the wellhead valves, inspection of the steam turbine rotor and bearings, testing and identifying failed tubes of the OEC heat exchangers and rectifying plant PLC control system.

Significant work was carried out during 2006 and 2007 which resulted in the GCCU unit becoming operational in June 2007.

Failure analysis of the OEC heat exchanger tubes revealed that they need to be replaced with more corrosion resistant material. Subsequently, retubing of the heat exchanger tubes was undertaken in early 2009 and the unit was commissioned in June 2009. Both of the Aluto power plant units have been under operation since commissioning.

**Keywords:** Aluto project, plant rehabilitation, pilot power plant, binary and combined cycle unit

### INTRODUCTION AND BACKGROUND

The Aluto geothermal field is located in the lakes district region of Ethiopia, about 200km south of the capital Addis Ababa. Access to the site is along the main southern high way which proceeds to Kenya.

The Aluto Langano Geothermal Pilot Plant is the first geothermal plant to be built in Ethiopia. The power plant is owned and operated by the state power company, Ethiopian Electric Power Corporation (EEPCO). The plant is composed of two units, the geothermal combined cycle unit (GCCU), which uses the geothermal steam from the hotter wells LA3 and LA6, and the Ormat Energy Converter (OEC unit) which uses steam from the lower temperature wells LA4 & LA8 and brine from all four wells. The objectives of the pilot plant were to test the Aluto resource, identify any resource or plant-related issues that could affect the further development of geothermal power at Aluto, allow EEPCo personnel to gain operation and maintenance experience on a geothermal power plant, and to provide power to the national grid. The project was also designed to act as a catalyst for the development of larger follow-on geothermal plants in the area.

Although the production wells were drilled during the early 1980's, as exploration wells, the decision to build a geothermal pilot plant was made more than a decade later in the mid 1990's. During the exploration program, a total of six wells were drilled on the Aluto volcano of which five were found to be productive.

Ormat Industries Ltd of Israel built and installed the power plant under a turnkey contract from early 1997 until the middle of 1998. EEPCo assumed formal responsibility for the operation and maintenance of both the plant and well field after commissioning in the middle of 1998.

The designed power output of the pilot plant was 8.52 MWe (gross) and 7.28 MWe (net). Shortly after commissioning, the resource and plant began experiencing problems that eventually led to its shutdown in 2002.

In 2005, EEPCo issued an international tender for the rehabilitation of the Aluto plant and wellfield that was won by Geothermal Development Associates of USA. The primary objectives of the contract was to investigate the reported problems and carry out repairs on the plant, wellfield, gathering system, transmission line, plant control system and provide training for EEPCO personnel. Any additional failure discovered during the rehabilitation was to be given as a recommendation. The main rehabilitation contract was implemented beginning in February 2006 through June 2007 when the GCCU unit was put back into operation. Under a contract amendment, the retubing of the OEC unit was carried out from late 2008 until early 2009 and the unit was put back into operation in July 2009.

## PROBLEMS IDENTIFIED

A number of problems were identified during the initial operation of the plant and subsequent to its shut down in 2002 which formed the contract terms of reference for the rehabilitation work. These problems can be generally classified into two groups: those relating to the resource and those relating to the plant/steamfield.

### *Resource related problems:*

- Wells unable to deliver steam at design pressure
- Solid emission from some of the production wells
- Mineral deposition down hole and in surface fluid gathering system

### *Plant/ steamfield related problems*

- Leakage of wellhead valves
- Steam turbine bearing wear and high bearing temperature
- Heat exchanger tube failure
- Cooling tower fan problems
- Operational difficulties with plant control & monitoring software
- Transmission line problems

## REHABILITATION WORK PERFORMED

### *Resource related rehabilitation works*

#### Low operating pressure of wells LA3 & LA6

The most serious problem observed during the initial operation of the plant was that the operating pressure of wells LA-3 and LA-6 falling significantly lower than the design inlet pressure of the steam turbine. Subsequent well tests performed by GDA, as part of this contract, also showed that the wells are unable to sustain the operating pressure that the turbine was originally designed for. To address this problem, it was necessary to review the design of the turbine and implement necessary engineering measures so that it can operate at lower steam inlet pressures. After thorough review of the characteristics of the wells a recommendation was made to remove the first two stages of the turbine blades to enable the turbine accept the design flow rate of steam at the reduced inlet pressure. This measure of removing some of the stages (de-staging) would allow the wells to operate reliably, although at a slight reduction in power generated from the steam turbine.

The recommendation to remove the stages was also based on other practical issues. For example during the rehabilitation work, visual inspection of the first and second stages showed that they would require major repairs or outright replacement with new components. The de-staging process is reversible and if the operating pressure of future new wells reaches and maintains the original design pressure, the removed stages can be reinstated.

#### Solid emission from wells:

Some of the production wells were reported as emitting solids into the fluid gathering system resulting in blockage of the piping and parts of the plant. Most of the wells only discharge solids during the initial opening; however, well LA8 tends to produce sand & debris even during normal operation. In order to resolve this problem, two solutions were proposed. The first was to design & implement an operational procedure that will ensure that wells are vented to atmospheric discharge vessels (silencers) during initial opening until the flow stabilizes and become clear of solids. The second solution is to install strainers on the wells which continuously discharge solids such as well LA8.

#### Mineral deposition:

Due to the reported blockage in some wells and the suspected decline in flow, detail investigation of the condition of the well bores was carried out using go-devil tool and sinker bars to determine the open diameters and current total depths of the wells. The sinker bar/go-devil logging in well LA-4 conclusively showed that the well has a major scale deposition with the greatest restriction probably near a depth of 1000 m. The sinker bar/go-devil logging in LA-8 discovered a major blockage of uncertain nature at a depth of 700 m. LA-3 had little or no loss of total depth but LA-6 had lost some total depth. It was determined that the thick scale recovered from go-devils in LA-4 would

explain a large reduction in the output of LA-4. The recovered fragments of scale from LA4, along with the depth and shape of the diameter reduction, strongly suggests that this scale is carbonate scale that formed as a result of flashing of the liquid in the wellbore. A major blockage of uncertain nature was also observed at 1,461.7 m in LA-7. As this is a reinjection well, it is not known how this blockage will impact the well's ability to accept fluid. Well work-overs were proposed for those wells with blockage.

#### ***Plant and steamfield related works***

##### **Rehabilitation of the steam turbine**

The major repair work undertaken on the plant involved the work done to rectify the problems on the GCCU steam turbine. During inspection of the turbine rotor, in addition to the repairs defined in the rehabilitation contract, significant damage to the rotating blades, seal hub and shaft journal area was observed. Damages to the rotor shaft and bearing were also noted. Subsequently, a recommendation to repair the turbine blades and the hub were made to EEPSCO.

There was heavy corrosion and deposits on parts of the rotor blades (Figure 1). The interstage drains were clogged and filled with hard deposits which were later cleared of the deposition and cleaned.

There was very little scale deposited on the first stage nozzles, where it normally is found. A soft scale was found in the first stage rotating blades and it was deposited along the outer section of the blades, near the shrouds.



**Figure 1:** Corrosion of the turbine blades

A section of the rotor labyrinth steam seal appeared to have been damaged due to wear from contact with a heavy scale deposit or a foreign object. However, there was no corresponding wear on the mating stationary labyrinth seal (Figure 2).

Other than the damage to shaft bearing journal, and to oil and steam seals and corrosion on rotating and stationary blades, the rest of the turbine appeared to be in reasonably good condition and the design and build quality appeared to be good.



### Figure 2: Worn Labyrinth seal

The stationary labyrinth steam seals were in generally excellent condition.

An investigation was conducted to decide whether it would be better to repair the rotor in Ethiopia or send it overseas.

Several facilities in Addis Ababa were visited and the Ethiopian Airlines (EA) shop appeared to be an excellent and well-equipped facility and a strong candidate for a local repairs. However, it was discovered that the EA shop repairs damaged shafts by a plating process and the maximum thickness they could plate was 1 mm. The scoring on the turbine shaft was deeper than that.

The decision to repair the shaft in Addis was further complicated in part because the rotor must be disassembled for repair and drawings or experience with this particular rotor design were not available. The needed turbine drawings were not provided as part of the original plant contract.

GDA's recommendation was that the rotor be shipped to Texas, USA, where identical turbines from other US geothermal plants are routinely repaired.

### **Wellhead valve repairs**

The wellhead valves at Aluto had been in service ever since the wells were drilled and completed in the early 80's. Major problems observed included, severe corrosion of the valve stem, corrosion and in some instances jamming of the gate-segment assembly, erosion & wear of the body-seats, damage of the valve gland and bearings. Despite these problems, the valve bodies were in very good condition. It was decided that the most cost-effective solution was to procure valve spare parts and carry out maintenance of the valves in stead of buying new wellhead valves, which also involve long lead times. Accordingly, spare parts enough to service most of the 10" and 2" wellhead valves at the project site were purchased and the maintenance carried out. After completing the repair each valve was pressure tested to the applicable pressure to ensure that the repair work was satisfactory. The reconditioned valves were subsequently installed on the geothermal wells.

### **Repairs to Heat Exchanger Tubes**

The OEC was taken out of service in 1999 due to vaporizer tube leaks. Originally, a total of twenty (20) leaking tubes were reported by EEPCo.

The vessel is a shell and tube heat exchanger with approximately 1,641 tubes of welded 316L stainless steel and 20 mm (3/4") OD by 0.035" wall thickness (20 gages) dimensions. The tube length is approximately 11.6 m (38').

GDA was tasked with identifying the cause of the leaks, repairing the leaks, if possible putting the unit into operation and making recommendations for a long-term solution.

A tube failure analysis of two leaking tubes was carried out by Jonas Inc. laboratories of Wilmington, USA. The major finding of this analysis was that the root cause of the pitting was the use of wrong tubing material, 316L austenitic stainless steel, which seemed to be not suitable for the chemistry of the Aluto wells. It also found that the tube leaks were caused by tube ID pitting, which occurred during the initial service of the heat exchanger. Additional pitting could have happened during the subsequent six years of unprotected layup. The pitting seemed to be more frequent at the bottom part of the tubes where there was a liquid layer of condensed steam. It was expected that pits were present on the ID of most of the heat exchanger tubes. Jonas concluded that, with the same composition of steam and operating conditions, the pitting will continue and the heat exchanger will be unusable within a few years, therefore total replacement of the tubes would be necessary.

A second analysis was carried out by PowerChem, of Minden, Nevada, USA. PowerChem's final report provided a number of recommendations that related to operator training in order to improve the steam quality, testing and startup procedures, etc as well as implementation of a corrosion mitigation treatment program. The practicality and feasibility of isolating (by plugging) the failed tubes and putting the unit into operation, as a temporary solution, was extensively investigated. However, successive pressure tests after plugging leaky tubes proved to be unsuccessful due to discovery of more leaky tubes after each pressure test. It was decided to replace the failed tubes on the vaporizer and the first two passes of the preheater with more corrosion resistant tube material – 2205 Duplex stainless steel.

### Other Rehabilitation Works performed

Various additional tasks and reviews were carried out during implementation of the rehabilitation phase. A number of recommendations on well work-over, staffing and training, establishment of plant & resource monitoring program, required plant spare parts were submitted.

In addition, investigation of the problems and putting the plant control system (Programmable Logic Control) back into operation was carried out.

The Fiber Optic communication link between the plant and the Adami Tulu sub station was repaired

Investigating the problem and undertaking the necessary repair, including supply of parts, for the cooling tower fans & proposing long-term solutions was made.

Inspecting the problems and reviewing the design of the 15 kV transmission line between the power plant and the substation and providing recommendations to enable reliable operation was done.

### **FUTURE WORKS**

A number of follow-on tasks are required to be implemented to complete the rehabilitation work and ensure long-term reliable operation of the plant and resource. Some of these follow-on tasks include:

- Work-over of wells which have blockage in the wellbore
- Implement chemical inhibition system for those wells with chemical deposition
- Implement resource (reservoir & geochemical) and plant performance monitoring program

### **CONCLUSION**

Geothermal energy is one of the available renewable energy sources in Ethiopia and can play an important role in supporting the current generation. Geothermal power is capable of providing a base load to supplement the existing mainly hydro-based power generation system. Unlike hydro power plants, geothermal power also has the benefit of not being affected by drought patterns.

Based on the experience gained during the rehabilitation work, the following observations and suggestions are made:

1. The Aluto plant is a relatively complex plant to operate and maintain when compared to back pressure or even condensing flash plants of similar size. Due to its complexity, it requires oversight and maintenance by an experienced team of plant and resource specialists.
2. In order to expand the use of geothermal energy in Ethiopia, training of Ethiopian personnel in the various aspects of plant and wellfield operations and maintenance should be an ongoing process.
3. An experienced geoscientist, responsible for the long-term operability of the wellfield, including resource monitoring, scaling monitoring and mitigation would be beneficial.
4. Successful operation of a geothermal plant requires adequate and timely supply of tools, equipment and consumables, therefore a well-organized spare parts procurement and storage/retrieval system must be put in place.

### **ACKNOWLEDGEMENTS**

The rehabilitation work described in this paper was possible due to the participation of a number of GDA engineers and scientists in addition to EEPCO personnel. The input of Dick Benoit and Martin Booth on the resource side, Bob Thomasson, Larry Bandt, Dave Mendive and Sean Geffert on the power plant aspects was crucial. The input of EEPCO project coordinators Mulugeta Asaye and Merga Tassew and several other personnel through out the implementation period was significant. Thanks are due to Yvette Hamacek for reviewing the draft of this paper.

### **REFERENCES**

Geothermal Development Associates, Unpublished Report Submitted to EEPCO, "Final Project Completion Report - Consultancy Services and Repair of the Aluto Langano Geothermal Pilot Power Plant, Contract RHGP 1/97", June 2008.

Geothermal Development Associates, Unpublished Report Submitted to EEPCO, "Contract TOR Reports – Volume 1 - 3", July 2008.

Jonas Inc. Unpublished Report Submitted to EEPSCO "Analysis of Heat Exchanger Tube Pitting - Aluto-Langano Geothermal Pilot Plant", June 2006

PB Power, Unpublished Report Submitted to EEPSCO "Aluto-Langano Geothermal Pilot Plant Project Power Plant and Resource Review Report", May 2000.

Powerchem, Unpublished Report Submitted to EEPSCO "Aluto-Langano Geothermal Pilot Plant OEC Vaporizer Corrosion - Evaluation and Mitigation Plan", September 2006.